

Rosemary Inn, Rock-A-Bye Cabin (Building No. 388)
Olympic National Park
Barnes Point, Lake Crescent
Port Angeles Vicinity
Clallam County
Washington

HABS No. WA-185-M

HABS
WASH
5-POAN.V,
2M-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA


Historic American Building Survey
National Park Service
Western Region
Department of the Interior
San Francisco, California 94107

HABS
WASH
5-POAN.V,
2M-

NATIONAL PARK SERVICE
Department of the Interior

HISTORIC AMERICAN BUILDING SURVEY
ARCHITECTURAL DATA FORM

STATE WASHINGTON	COUNTY CLALLAM	TOWN OR VICINITY Approximately 20 miles southwest of Port Angeles
HISTORIC NAME OF STRUCTURE (include source for name) Rosemary Inn, "Rock-a-Bye" Cabin		HABS NO. WA-185-M
SECONDARY OR COMMON NAMES OF STRUCTURE Bldg. No. 386		
COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park.		
DATE OF CONSTRUCTION (include source) pre-1926 (Historic Structure Report)	ARCHITECT(S) (include source) Builder and Craftsman: John Daum (HRS, 1983)	
SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association.		
STYLE (If appropriate) Craftsman-style cabin		
MATERIAL OF CONSTRUCTION (include structural systems) Wood-frame construction set on 6 x 6 posts on piers and blocks		
SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) L-shape: 18' x 11'		
EXTERIOR FEATURES OF NOTE 1-story; wood-shingled hip roof with projecting hip-roofed entry porch on south; exposed rafters and extended eaves; board and batten siding with wood shingles above; entry porch supported by log posts; wide board porch rail; multi-paned and single-pane hinged and casement sash; multi-paned glass and wood paneled "dutch" entry door.		
INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; painted vertical board wainscoting with board and battens above.		
MAJOR ALTERATIONS AND ADDITIONS, WITH DATES		
PRESENT CONDITION AND USE Fair; Vacant		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 National Register Listing, 1979		
COMPILER, AFFILIATION Gretchen A. Luxenberg, National Park Service	DATE July, 1988	



Rock-a-bye Building #386